



Central Portal for  
Philippine Government  
Procurement Opportunities

## Bid Notice Abstract

### Request for Quotation (RFQ)

**Reference Number** 8638879  
**Procuring Entity** DEPARTMENT OF SOCIAL WELFARE AND DEVELOPMENT - REGION V  
**Title** LABOR & REPLACEMENT OF PARTS AND MATERIALS OF DSWD FO V SERVICE VEHICLE ISUZU WITH PLATE NO. SAB 4412.  
**Area of Delivery** Albay

|  |   |                              |                     |
|--|---|------------------------------|---------------------|
| <b>Solicitation Number:</b>              | NF 2204-0131  | <b>Status</b>                | <b>Pending</b>      |
| <b>Trade Agreement:</b>                  | Implementing Rules and Regulations  | <b>Associated Components</b> | 1                   |
| <b>Procurement Mode:</b>                 | Negotiated Procurement - Small Value Procurement (Sec. 53.9)  | <b>Bid Supplements</b>       | 0                   |
| <b>Classification:</b>                   | Goods   | <b>Document Request List</b> | 0                   |
| <b>Category:</b>                         | Vehicle Repair and Maintenance  | <b>Date Published</b>        | 03/05/2022          |
| <b>Approved Budget for the Contract:</b> | PHP 123,000.00  | <b>Last Updated / Time</b>   | 02/05/2022 12:50 PM |
| <b>Delivery Period:</b>                  |   | <b>Closing Date / Time</b>   | 06/05/2022 12:00 PM |
| <b>Client Agency:</b>                    |   |                              |                     |
| <b>Contact Person:</b>                   | Judex Donnel G. Llamoso<br>BAC Secretariat<br>Magnolia St., PBN<br>Buragwis,<br>Legazpi City<br>Albay<br>Philippines 4500<br>63-52-4805670<br><br>fo5bacsec2021@gmail.com |                              |                     |

#### Description

LABOR & REPLACEMENT OF PARTS AND MATERIALS OF DSWD FO V SERVICE VEHICLE ISUZU WITH PLATE NO. SAB 4412.

#### LABOR:

Pulldown Transmission Replace Clutch Parts  
 Reface ply wheel  
 Replace Upper Ball Joint Both Sides  
 Replace Lower Ball Joint Both Sides  
 Replace Front Shock Absorber Both Side  
 Replace Rear Shock Absorber Both Side  
 Replace Shackle Bushing  
 Reface Rotor Disk  
 Reface Brake Drum  
 Repack Fron Hub Bearing  
 Preplace Hose Connecting Intercooler Right Hand  
 Replace Fuel Filter  
 Replace Tie Rod Bar Both Side  
 Replace Tie Rod End Both Side  
 Replace All Belt

Perform Wheel Alignment Lamber and Caster

PARTS:

1 pc Clutch Disk  
1 pc Pressure Plate  
1 pc Release Bearing  
1 pc Pilot Bearing  
3 liters Transmission Oil  
2 pcs Upper Balljoint  
2 pcs Lower Balljoint  
2 pcs Front Shock Absorber  
2 pcs Rear Shock Absorber  
8 pcs Shackle Bushing  
2 pcs Hub Oil Seal  
1 can Grease  
1 pc Hose Connecting Intercooler Right Hand  
2 pcs Fuel Filter A  
2 pcs Fuel Filter B  
2 pcs Tie Rod Bar  
2 pcs Tie Rod End  
1 pcs A/C Belt  
1 pc Alternator Belt  
3 pc Brake Cleaner  
1 bot Misc

**Created by** Judex Donnel G. Llamoso

**Date Created** 02/05/2022

The PhilGEPS team is not responsible for any typographical errors or misinformation presented in the system. PhilGEPS only displays information provided for by its clients, and any queries regarding the postings should be directed to the contact person/s of the concerned party.